

4. ENGINE REMOVAL/ INSTALLATION

Engine mounting bolt torque values are changed for 1982 and they are shown below. Refer to page 5-4 for installation instructions.

