
Indicators

If one of these indicators does not come on when it should, have your dealer check for problems.





Comes on briefly when the ignition switch is turned on

If it comes on while riding: (P107)

CBR1000RA only

Comes on when the ignition switch is turned on. Goes off when your speed reaches approximately 6 mph (10 km/h).

If it comes on while riding: (P109)