Instruments (Continued)

The peak hold segment keeps to show the maximum engine RPM temporarily.

Example: Engine revolutions per minutes 10,000 r/min (rpm)

