


E 9

E-10

Moteur démarrage



MK53-E1000

Item d'entretien	T.D.R.	N° de réf.	N° de pièce	Description	N° de requis			N° de série	Code de zone
					XL600	LMF	RMg		
		34)	91032-MK5-004	ROULEMENT A AIGUILLES, 12X17X17.4(KOYO)	2	2	2		
		35	91033-MK5-003	ROULEMENT A AIGUILLES, 12X17X10(NTN)	1	1	1		
			91033-MK5-004	ROULEMENT A AIGUILLES, 12X17X10(KOYO)	1	1	1		
		36	91061-MK5-013	ROULEMENT A AIGUILLES, 34X39X23.7(TOYO)	1	1	1		
		37	91309-425-003	JOINT TORIQUE, 24.4X3.1(ARAI)	1	1	1		
		38	91312-PC6-003	JOINT TORIQUE, 57.8X2.4	1	-	-	5006225	
		39	94111-05000	RONDELLE ELASTIQUE, 5MM	3	3	3		
		40	94303-05080	GOUJON D'ASSEMBLAGE, 5X8	1	-	-	5006225	
					-	1	1		
		41	94520-32000	CIRCLIP INTERIEUR, 32MM	1	-	-	5006224	
		42	95800-06055-07	BOULON DE BRIDE, 6X55	2	2	2		
		43	96000-06016-07	BOULON DE BRIDE, 6X16	1	1	1		
		44	96100-60010-00	ROULEMENT A BILLES RADIAL,	6001	-	1	1	
					1	-	-	5006225	
		45	96100-62010-00	ROULEMENT A BILLES RADIAL,	6201	1	-	-	5006224