


L 2

F-27

Wire harness •
Ignition coil • Horn



B371-42

Service item	F.R.T.	Ref. No.	Part No.	Description	Reqd. No.				Serial No.	Area code
					GL1000	GL1000	LTD K1	K2		
		16	32215-371-000	SUB CORD, HORN	1	1	1	1		A,CM
			32215-371-620	SUB CORD, HORN		1	1	1		E,ED,F,G
			32215-371-680	SUB CORD, HORN	1	1	1	1		DK,DM,U
		17	34570-371-671	RESISTOR, HEADLIGHT & TAILLIGHT	1	1	1	1		A,CM
		18	34530-371-003	RESISTOR COMP. (TOYO)	1	1	1	1		
		19	33114-371-000	PROTECTOR, CORD	1	1	1	1		
		20	33100-300-023	HORN ASSY. (MITSUBA)	1	1	1	1		A,CM,DK,DM,U
		21	38100-371-620	HORN COMP.						
			38100-371-621	HORN ASSY.		1			2040165	ED,F,G
									2040165	E,ED,F,G
										E,ED,F,G
		22	38200-371-153	BOX ASSY., FUSE	1	1	1	1		
		23	38300-292-670	RELAY ASSY., WINKER	1	1	1	1		
		24	38300-371-681	RELAY ASSY., WINKER	1					A,CM
										DK,DM,U
			38300-371-682	RELAY ASSY., WINKER (MITSUBA)		1			2022930	DK,DM,U
			38300-371-683	RELAY ASSY., WINKER						DK,DM,U
			38306-107-670	SUSPENSION, WINKER RELAY	1	1	1	1		DK,DM,U
										E,ED,F,G
										ED,F,G,U
										DK,DM,E,ED,F,G,U
										DK,DM,E,ED,F,G,U
										A,CM
		25	38306-107-670	SUSPENSION, WINKER RELAY	1	1	1	1		
		26	38306-292-000	SUSPENSION, WINKER RELAY	1	1	1	1		
		27	38420-371-671	RESERVE UNIT, LIGHTING (STANLEY)	1	1	1	1		DK,DM,E,ED,F,G,U
										A,CM
		28	93500-03012-0A	SCREW, PAN, 3X12	2	2	2	2		
		29	93500-05006-0A	SCREW, PAN, 5X6	2	2	2	2		

1979.04.10

L2