


# 22. WIRING DIAGRAM



- Bl .....Black
- Y .....Yellow
- Bu .....Blue
- Lb .....Light Blue
- G .....Green
- Lg .....Light Green
- R .....Red
- P .....Pink
- W .....White
- Br .....Brown
- O .....Orange
- Lt .....Light
- Pk .....Pink
- Gr .....Grey

IGNITION SWITCH	BAT	IGN	TL	TL	P	LOCK
ENGINE STOP SWITCH	IGN	BATS	OFF	RUN	OFF	
STARTER SWITCH	BAT2	ST	HL	BATS	FREE	PUSH
DIMMER SWITCH	HL	LD	HL	HL	FREE	PUSH
HORN SWITCH	HL	BAT2	FREE	PUSH		
TURN SIGNAL SWITCH	W	R	L	P	P	L
	W	R	L	P	P	L
	W	R	L	P	P	L
	W	R	L	P	P	L